

Saab 9-3 Saab Bluetooth Hands Free - Phone compatibility list

Version 5.0 Released: 2010-11-18

The below list is to be used as an indication of the functional compatibility that can be expected.

Tests have been made on the listed systems and phone software's and is only valid for these specific combinations.

Abbreviations:

OK	Function supported
COK	Function partly supported / supported under certain conditions
NOK	Function not supported
NT	Function not tested
HFS	Hands Free System
BTP	Bluetooth Phone

See Comments / Deviations for comments and general observations for each phone

Production interval per PBIS software release

Saab Bluetooth Handsfree S/W version	PBIS S/W partnumber	Production interval	Body style	Start VIN interval	End VIN interval
4.0 (new HW: 13304898)	13304899 (not backwards compatible with older HW)	MY11 (Q4 and onwards)	Sedan / Wagon	B1303670	-
			Convertible	-	-
3.0	12842433	MY09-MY11 (until Q3)	Sedan / Wagon	91013796	-
			Convertible	296001565	-
2.0	12778933	MY07-MY09 (until Q3)	Sedan / Wagon	81000121-81000136 71139708-71140015	91013796
			Convertible	676109690	296001565
1.0	1.0	MY07	Sedan / Wagon	71016876-71017248	71139708-71140015
			Convertible	776003483	676109690

Supported phones	Phone software The software version in your phone (refer to manual or manufacturer on how to check it)	Saab Bluetooth Handsfree system S/W version. See production interval table for detailed information	Bluetooth Connection Stability of the connection between phone and vehicle system	Hands Free Dialling ability to dial from vehicle HMI	Phone book Access in vehicle HMI	Call list Access in vehicle HMI	Private mode Switch audio between vehicle and phone	Cradle part number	Comments / Deviations
Apple									
Apple iPhone 3G	2.0.2(sc1)	3.0	NOK ¹⁾	OK	NOK ¹⁾	OK	OK	Not available	1) Phone not recommended to use with UHP Phone book entries can cause Bluetooth connection to fail.
Apple iPhone 3G	3.0.1	3.0	OK	OK ¹⁾	NOK	OK	OK	Not available	1) Sometimes no ring signal in Hands Free system
Apple iPhone 3GS	4.0 (8A293)	4.0	OK	OK ¹⁾	OK	OK	OK	Not available	1) Have to choose "Source - UHP" in phone meny to direct sound to car.
Apple iPhone 4	4.1 (8B117) 02.10.04	4.0	OK ¹⁾	OK ²⁾	OK	OK	OK	Not available	1) If Bluetooth is disabled via Phone and then enabled again no connection is established. The connection then has to be initiated via HFS instead. 2) If incoming call is answered from Phone the call will be transferred from Hands free to Phone.
Blackberry									
Blackberry 8110	--	3.0	OK	OK	OK ¹⁾	OK	OK	Not available	1) SIM contacts isn't transferred
Blackberry Bold	v4.6.0.185	3.0	OK	OK ¹⁾	OK	OK	OK	Not available	1) Sometimes no ring signal in Hands Free system
HTC									
HTC Desire	Android 2.1 (update 1.21.405.2)	4.0	COK ¹⁾	OK ²⁾	OK	OK	OK	Not available	1) Sometimes first pairing attempts fail. As long as it's paired once everything works fine. 2) If a call is answered by using the Phone you have to manually transfer audio to Hands free by choosing "BT headset on" in Phone menu.
HTC HD2	5.2.21869	4.0	OK	OK	OK	OK	OK	Not available	
HTC Hero	Firmware1.5 S/W 1.0.0.A6288	3.0	OK ¹⁾	OK	COK ^{2,3)}	OK ²⁾	OK	Not available	1) Sometimes instability issues at start up 2) Some special characters not shown 3) Some contacts not transferred correctly
HTC Magic	Firmware 1.5	3.0	OK	COK ¹⁾	OK ³⁾	OK ²⁾	OK	Not available	1) Some times not ring signal. 2) Some special characters not shown
HTC P5500 Touch Dial	1.58.16.27	3.0	OK	OK	OK ¹⁾	NOK	OK	Not available	1) Some special characters not shown
HTC Touch Diamond P3700	1.00.25.05	3.0	OK	OK	NOK	NOK	OK	Not available	
LG									
LG Chocolate BL40	BL40-MSM 76XX-D10d-OCT-10-2009-SE	4.0	COK ¹⁾	COK ¹⁾	COK ²⁾	OK	OK	Not available	1) At times incoming calls cannot be accepted / rejected. 2) Hands free call list is not transferred from Phone.
LG GB250	GB250AT_V10a	3.0	NOK	NT	NT	NT	NT	Not available	Phone restarts and disconnects. Stability issues seen. Phone is not recommended
LG GD900	GD900AT_V10c	3.0	OK	NOK	NOK	NOK	OK	Not available	Phone is not recommended
LG GW620	1.5 (2.6.27)	4.0	OK	OK	OK	OK	OK	Not available	
LG KP500	HP500AT_V10d	3.0	NOK	NT	NT	NT	NT	Not available	Phone restarts and disconnects. Stability issues seen. Phone is not recommended
LG KU990	KU990_V10g	3.0	OK	OK	NOK	NOK	OK	Not available	
LG PRADA KE850	Unknown	2.0	OK ¹⁾	OK ²⁾	OK ³⁾	NOK ⁴⁾	OK	Not available	1) Disconnecting and re-connecting by interrupted Bluetooth connection in cell phone not working 2) Rejecting an incoming call causes an unobtainable tone in the calling phone. 3) Type information displayed as e.g. /1 and /2 etc instead of /W and /H for Work and Home phone number. 4) Not supported. Empty call list is "downloaded".
LG PRADA KE850	Unknown	3.0	OK	OK ¹⁾	OK ²⁾	NOK	OK	Not available	1) Low volume from Car side 2) Special characters not displayed

Supported phones	Phone software The software version in your phone (refer to manual or manufacturer on how to check it)	Saab Bluetooth Handsfree system S/W version. See production interval table for detailed information	Bluetooth Connection Stability of the connection between phone and vehicle system	Hands Free Dialling ability to dial from vehicle HMI	Phone book Access in vehicle HMI	Call list Access in vehicle HMI	Private mode Switch audio between vehicle and phone	Cradle part number	Comments / Deviations
Nokia									
Nokia 2600 Classic	V 05.61 18-04-08 RM-340	3.0	OK	OK	OK	OK	OK	Not available	
Nokia 2760	V 07.60	3.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Bluetooth is disconnected if entering 'private mode'.
Nokia 3100	V 05.02	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 060	1) Only cradle, no Bluetooth
Nokia 3109 / 3110 Classic	V05.50 14-08-07 RM237	2.0	OK ¹⁾²⁾	OK	OK ³⁾	OK	OK ⁴⁾	Not available	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Disconnecting and re-connecting by Power Mode Cycle or after disconnections not working 3) Type information displayed as e.g. /1 and /2 etc instead of /W and /H for Work and Home phone number. 4) Bluetooth is disconnected if entering 'private mode'.
Nokia 3110 Classic	V07.21	3.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Bluetooth is disconnected if entering 'private mode'.
Nokia 3720	10.16	4.0	OK	OK	OK	OK	NOK ¹⁾	Not available	1) Phone loses connection with car when user tries to move audio between phone <-> car.
Nokia 5310 XpressMusic	V 05.81 06-02-08 RM-303	3.0	OK ¹⁾	OK	OK ²⁾	OK	OK ¹⁾	Not available	1) Bluetooth is disconnected if entering 'private mode'. 2) Occasionally phone book not loaded.
Nokia 5630 XpressMusic	011.020	3.0	OK ¹⁾	OK	OK	COK ²⁾	OK	Not available	1) Sometimes phone book disappears if phone gets out of range 2) Some Call list entry remains even if call lists deleted in Phone
Nokia 5630 XpressMusic	12.020	3.0	OK	OK	OK	OK	OK	Not available	
Nokia 5800 XpressMusic	V21.0.025	3.0	OK ¹⁾²⁾	OK	OK	COK ³⁾	OK	Not available	1) Sometimes phone book disappears if phone gets out of range 2) Seen ocatons where bluetooth connection lost. Turno on/off bluetooth in phone solved issue. 3) Some Call list entry remains even if call lists deleted in Phone
Nokia 6020	V 03.52	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 332	1) Only cradle, no Bluetooth
Nokia 6021	V 03.83	2.0	OK	OK	OK	OK	OK	93 199 332	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Bluetooth is disconnected if entering 'private mode'. 3) vCard information displayed as e.g. /1 and /2 etc instead of /W and /H for Work and Home phone number.
Nokia 6100	V 05.51	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 061	1) Only cradle, no Bluetooth
Nokia 6110 Navigator	Symbian OS V03.51 Nokia firmware 11.52	2.0	OK ¹⁾²⁾	OK	NOK ³⁾	NOK ³⁾	NT	Not available	1) Radio is muted when connecting to Bluetooth and when changing profile in phone. 2) Disconnecting and re-connecting by interrupted Bluetooth connection in cell phone not working 3) Telephone does not support. Empty phone book and call list are "downloaded".
Nokia 6110 Navigator	Symbian OS V03.51 Nokia firmware 11.52	3.0	OK ¹⁾	OK	NT	NT	OK	Not available	1) Radio is muted when connecting to Bluetooth and when changing profile in phone.
Nokia 6151	V04.10 21-12-06 RM-200	2.0	OK ¹⁾²⁾	OK	OK ³⁾	OK	OK ⁴⁾	93 199 664	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Disconnecting and re-connecting by Power Mode Cycle or after disconnections not working 3) vCard information displayed as e.g. /1 and /2 etc instead of /W and /H for Work and Home phone number. 4) Bluetooth is disconnected if entering 'private mode'.
Nokia 6151	V04.10 21-12-06 RM-200	3.0	OK ¹⁾	OK	OK	OK	OK ²⁾	93 199 664	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Bluetooth is disconnected if entering 'private mode'.
Nokia 6220	V 5.15	1.0	OK	OK	NOK	NOK	NOK	93 199 062	Limited Display Function over Bluetooth
Nokia 6220 Classic	03.06 31-05-08	3.0	OK	OK	OK ¹⁾	OK	OK	Not available	1) Some special characters not shown
Nokia 6230	V 05.50	1.0	OK	OK	NOK	NOK	NOK	93 199 058	Limited Display Function over Bluetooth
Nokia 6230i	V 03.40	1.0	OK	OK	NOK	NOK	NOK	93 199 058	Limited Display Function over Bluetooth
Nokia 6233	V05.10 21-12-2006 RM-145	2.0	OK ¹⁾²⁾	OK	OK	OK	OK ³⁾	93 199 550	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Disconnecting and re-connecting by Power Mode Cycle or after disconnections not working 3) Bluetooth is disconnected if entering 'private mode'.
Nokia 6233	V05.10 21-12-2006 RM-145	3.0	OK	OK	OK	OK	NOK	93 199 550	
Nokia 6233	V5.60	3.0	OK	OK	OK	OK	OK ¹⁾	93 199 550	1) Bluetooth is disconnected if entering 'private mode'.
Nokia 6234	V 03.70	1.0	OK ¹⁾²⁾	OK	OK ³⁾	OK	OK ⁴⁾	93 199 575	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Disconnecting and re-connecting by Power Mode Cycle or after disconnections not working 3) vCard information displayed as e.g. /1 and /2 etc instead of /W and /H for Work and Home phone number. 4) Bluetooth is disconnected if entering 'private mode'.
Nokia 6280	V 03.81	1.0	OK ¹⁾²⁾	OK	OK ³⁾	OK	OK ⁴⁾	93 199 839	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Disconnecting and re-connecting by Power Mode Cycle or after disconnections not working 3) vCard information displayed as e.g. /1 and /2 etc instead of /W and /H for Work and Home phone number. 4) Bluetooth is disconnected if entering 'private mode'.

Supported phones	Phone software The software version in your phone (refer to manual or manufacturer on how to check it)	Saab Bluetooth Handsfree system S/W version. See production interval table for detailed information	Bluetooth Connection Stability of the connection between phone and vehicle system	Hands Free Dialling ability to dial from vehicle HMI	Phone book Access in vehicle HMI	Call list Access in vehicle HMI	Private mode Switch audio between vehicle and phone	Cradle part number	Comments / Deviations
Nokia 6288	V06.43 30-03-07 RM-78	2.0	OK ^(1,2)	OK	OK ⁽³⁾	OK	OK ⁽⁴⁾	93 199 839	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Disconnecting and re-connecting by interrupted Bluetooth connection in cell phone not working. 3) vCard information displayed as e.g. /1 and /2 etc instead of /W and /H for Work and Home phone number. 4) Bluetooth is disconnected if entering 'private mode'.
Nokia 6288	V06.43 30-03-07 RM-78	3.0	OK ⁽¹⁾	OK	OK	OK	OK ⁽²⁾	93 199 839	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Bluetooth is disconnected if entering 'private mode'.
Nokia 6300	V05.00 27-04-07 RM-217	2.0	OK ^(1,2)	OK	OK ⁽³⁾	OK	OK ⁽⁴⁾	Not available	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Disconnecting and re-connecting by Power Mode Cycle or after disconnections not working. 3) vCard information displayed as e.g. /1 and /2 etc instead of /W and /H for Work and Home phone number. 4) Bluetooth is disconnected if entering 'private mode'.
Nokia 6300	V05.00 27-04-07 RM-217	3.0	COK ^(1,2)	OK	COK ⁽³⁾	OK	OK ⁽²⁾	Not available	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Bluetooth is disconnected if entering 'private mode'. 3) Occasionally phone book not loaded at start up.
Nokia 6300	V 07.21	3.0	OK	OK	OK	OK	OK ⁽¹⁾	Not available	1) Bluetooth is disconnected if entering 'private mode'.
Nokia 6310	V 05.01	1.0	OK	OK	NOK	NOK	NOK	93 199 354	Limited Display Function over Bluetooth
Nokia 6310i	V 07.00	1.0	OK	OK	NOK	NOK	NOK	93 199 354	Limited Display Function over Bluetooth
Nokia 6500 Classic	V 06.61 26-03-08 RM-265	3.0	COK ⁽¹⁾	OK	OK	OK	OK ⁽²⁾	Not available	1) Some stability issues seen 2) Bluetooth is disconnected if entering 'private mode'.
Nokia 6500 Classic	V.09.48	3.0	OK	OK	NOK	OK	OK ⁽¹⁾	Not available	1) Bluetooth is disconnected if entering 'private mode'.
Nokia 6600i slide	V36.14(RM-570)	3.0	OK	OK	OK	OK	OK ⁽¹⁾	Not available	1) Bluetooth is disconnected if entering 'private mode'.
Nokia 6610	V 05.52	1.0	OK ⁽¹⁾	OK	NOK	NOK	NOK	93 199 063 ⁽²⁾	1) Limited display functions over Bluetooth 2) Nokia 6610i is not released for cradle mode since the performance of the antenna coupling is not sufficient
Nokia 6700	32.005	4.0	OK	OK	OK	OK	OK	Not available	
Nokia 6700Classic	V07.60	3.0	OK	OK	OK	OK	OK ⁽¹⁾	Not available	1) Bluetooth is disconnected if entering 'private mode'.
Nokia 6730	31.022	4.0	OK	OK	OK	OK	OK	Not available	
Nokia 6820	V 04.25 V 03.81	1.0	OK ^(1,2)	OK	OK ⁽³⁾	OK	OK ⁽⁴⁾	93 199 059	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Disconnecting and re-connecting by interrupted Bluetooth connection in cell phone not working. 3) vCard information displayed as e.g. /1 and /2 etc instead of /W and /H for Work and Home phone number. 4) Bluetooth is disconnected if entering 'private mode'.
Nokia 7020	05.20	4.0	OK	OK	OK	OK	NOK ⁽¹⁾	Not available	1) Phone loses connection with car when user tries to move audio between phone <-> car.
Nokia 7210	V 04.74	1.0	NOK ⁽¹⁾	OK	OK	OK	NA ⁽¹⁾	93 199 063	1) Only cradle, no Bluetooth
Nokia 7250	V 03.62	1.0	NOK ⁽¹⁾	OK	OK	OK	NA ⁽¹⁾	93 199 063	1) Only cradle, no Bluetooth
Nokia 7250i	V 05.30	1.0	NOK ⁽¹⁾	OK	OK	OK	NA ⁽¹⁾	93 199 063	1) Only cradle, no Bluetooth
Nokia E22	021.013	3.0	OK	OK	OK	OK	OK	Not available	
Nokia E51	200.34.36 24-04-2008RM-244	3.0	OK ⁽¹⁾	OK	NOK ⁽²⁾	NOK ⁽²⁾	OK	Not available	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Phone book and Call lists aren't downloaded
Nokia E65	3.0633.69.0006-02-08 RM208	3.0	OK ⁽¹⁾	OK	NOK ⁽²⁾	NOK ⁽³⁾	OK ⁽³⁾	Not available	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Telephone does not support. Empty phone book and call list are "downloaded". 3) Bluetooth is disconnected if entering 'private mode'.
Nokia E66	210.21.007 RM-343	3.0	OK	OK	OK	OK ⁽¹⁾	OK ⁽²⁾	Not available	1) last entry will always be shown even if removed in the phone 2) transfer call from phone to vehicle using phone HMI doesn't work. Use vehicle HMI instead
Nokia N70	V 5.0609.2.0.1 01-03-06 RM84	3.0	OK ⁽¹⁾	OK	NOK ⁽²⁾	NOK ⁽²⁾	OK ⁽³⁾	Not available	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Telephone does not support. Empty phone book and call list are "downloaded". 3) Bluetooth is disconnected if entering 'private mode'.
Nokia N70	V5.0638.3.0.1	3.0	OK	OK	NOK	NOK	OK ⁽¹⁾	Not available	1) Bluetooth is disconnected if entering 'private mode'.

Supported phones	Phone software The software version in your phone (refer to manual or manufacturer on how to check it)	Saab Bluetooth Handsfree system S/W version. See production interval table for detailed information	Bluetooth Connection Stability of the connection between phone and vehicle system	Hands Free Dialling ability to dial from vehicle HMI	Phone book Access in vehicle HMI	Call list Access in vehicle HMI	Private mode Switch audio between vehicle and phone	Cradle part number	Comments / Deviations
Nokia N73	V 3.0638.0.0.1 30-10-2006 RM-133	2.0	OK ¹⁾²⁾	OK	NOK ³⁾	NOK ³⁾	OK ²⁾	Not available	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Disconnecting and re-connecting by Power Mode Cycle or after disconnections not working 3) Telephone does not support. Empty phone book and call list are "downloaded". 4) Bluetooth is disconnected if entering 'private mode'.
Nokia N73	V 3.0638.0.0.1 30-10-2006 RM-133	3.0	OK ¹⁾²⁾	OK	NOK ³⁾	NOK ³⁾	OK ⁴⁾	Not available	1) Radio is muted if any button is pressed on phone, or at key lock on/off, if phone is not in 'silent mode'. 2) Disconnecting and re-connecting by Power Mode Cycle or after disconnections not working 3) Telephone does not support. Empty phone book and call list are "downloaded". 4) Bluetooth is disconnected if entering 'private mode'.
Nokia N73	V4.0747.3.1.0.1	3.0	OK	OK	NOK	NOK	OK ¹⁾	Not available	1) Bluetooth is disconnected if entering 'private mode'.
Nokia N78	12.046 25-06-2008 Custom Version 12.046.051.1	3.0	OK ¹⁾	OK	OK ²⁾	OK ³⁾	OK ⁴⁾	Not available	1) Some Bluetooth stability issues seen 2) SIM Contacts isn't transferred 3) No number matching to SIM contacts 4) Reconnect using hands free system not possible
Nokia N82	V 20.0.06228-02-08 RM-313	3.0	OK	OK	NOK	NOK	OK	Not available	
Nokia N86	11.042	3.0	OK	OK	OK	OK	OK	Not available	
Nokia N900	10.2010.19.1	4.0	COK ¹⁾	COK ²⁾	NOK ¹⁾	NOK ¹⁾	OK	Not available	1) Phonebook and calls lists are not transferred from Phone. 2) Some ringtones are not compatible with Hands free (no ringtone will be heard).
Nokia N97	V11.0.021	3.0	OK	OK	OK	OK	OK	Not available	
Nokia N97 Mini	12.0.110	4.0	OK	OK	OK	OK	COK ¹⁾	Not available	1) Loses connection to Hands free when transferring audio to Phone if the ignition is off.
Nokia X6	21.0.004	4.0	OK	OK	OK	OK	OK	Not available	
Motorola									
Motorola E550	-	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 053	1) Only cradle, no Bluetooth
Motorola MOTOKRZR K1	R4527_G 08.22.11R DSP: 633 43400	2.0	OK ¹⁾	OK ²⁾³⁾⁴⁾	OK ⁵⁾	OK	OK	Not available	1) Disconnecting and re-connecting by Power Mode Cycle or after disconnections not working 2) Calls to busy cell phone can not be closed with steering wheel button, only on cell phone. 3) Bluetooth is disconnected if entering 'private mode'. 4)When calling busy number, network hangs up. 5) vCard format not supported by phone
Motorola MOTORAZR V3xx	R26111LD_U_ 96.06.738R DSP: 516 20000	2.0	NOK ¹⁾²⁾	NOK ¹⁾³⁾	OK ⁴⁾	OK	OK	Not available	1) Bluetooth connection causes cell phone to restart spontaneously every 1,5 min. 2) Disconnecting and re-connecting by Power Mode Cycle or after disconnections not working 3) Bluetooth is disconnected if entering 'private mode'. 4) vCard format not supported by phone
Motorola MOTORAZR V3xx	R26111LD_U_ 96.06.738R DSP: 516 20000	3.0	NOK ¹⁾²⁾	NOK ¹⁾³⁾	NOK	NOK	NOK	Not available	1) Bluetooth connection causes cell phone to restart spontaneously every 1,5 min. 2) Disconnecting and re-connecting by Power Mode Cycle or after disconnections not working 3) Bluetooth is disconnected if entering 'private mode'.
Motorola MOTORIZR Z3	R4528_G 08.01.05R DSP: 633 53500	2.0	OK ¹⁾	OK ²⁾	OK ³⁾	OK	OK	Not available	1) Some instability. On one occasion phone was unable to connect to car after pairing. 2) Bluetooth is disconnected if entering 'private mode'. 3) vCard format not supported by phone
Motorola MOTORIZR Z3	R4528_G 08.01.05R DSP: 633 53500	3.0	OK	OK	OK ¹⁾	OK	OK	Not available	1) SIM contacts isn't transferred
Motorola V300	V TRIPLETS_G OB.09.37R	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 053	1) Only cradle, no Bluetooth
Motorola V400	V TRIPLETS_G OB.08.AAR_A	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 053	1) Only cradle, no Bluetooth
Motorola V500	V TRIPLETS_G OB.09.38R	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 053	1) Only cradle, no Bluetooth
Motorola V525	V TRIPLETS_G OB.09.38R V	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 053	1) Only cradle, no Bluetooth
Motorola V600	V TRIPLETS_G OB.09.38R V	3.0	OK	OK	OK	OK	OK	Not available	
Samsung									
Samsung C6625	C6625XBID1	3.0	OK	NOK ¹⁾	OK	OK	OK	Not available	1) Sometimes Phone call stays active even if call is ended via HFS
Samsung E2210 B	E2210BBXBID1	3.0	OK	OK ¹⁾²⁾	OK	OK	OK	Not available	1) Answering using BTP no audio in HFS 2) Sometimes no ring signal in HFS
Samsung Galaxy GT-15700	Base SW: 2.6.27 Program SW: 1.5	4.0	OK	OK	COK ¹⁾	COK ²⁾	OK	Not available	1) Phonebook and Call lists only shows the main number for each contact, not the total vCard information. 2) Occasionally call lists are lost. Ok after system restart.
Samsung GT-S5230	S5230XBIG2	3.0	OK	OK	NOK	NOK	OK	Not available	

Supported phones	Phone software The software version in your phone (refer to manual or manufacturer on how to check it)	Saab Bluetooth Handsfree system S/W version. See production interval table for detailed information	Bluetooth Connection Stability of the connection between phone and vehicle system	Hands Free Dialling ability to dial from vehicle HMI	Phone book Access in vehicle HMI	Call list Access in vehicle HMI	Private mode Switch audio between vehicle and phone	Cradle part number	Comments / Deviations
Samsung i8910 HD	I8910xxif7	3.0	OK ¹⁾	OK ²⁾	OK	OK	OK	Not available	1) some pairing issues seen. 2) sometimes no ringtone in HFS
Samsung Omnia	1.3.5.0	4.0	OK	OK	OK	OK	OK	Not available	
Samsung SGH-D900	D900XBFJ2	2.0	OK	OK ¹⁾	NOK ²⁾	NOK ²⁾	OK ¹⁾	Not available	1) Calls are transferred to cell phone ("private mode") if answered on cell phone 2) Telephone does not support. Empty phone book and call list are "downloaded"
Samsung SGH-F300	F300CPGD2	2.0	OK	OK	NOK	NOK	OK	Not available	
Samsung SGH-F300	F300CPGD2	3.0	OK	OK	OK	NOK	OK	Not available	
Samsung SGH-i200	CE-Operativsystem 5.2.19214 (build 19214.1.0.4) Radio version I200XBHE3 RIL Version 2.002	3.0	COK ¹⁾	OK ²⁾	NOK	NOK	OK	Not available	1) automatic connection to hands free system during incoming and outgoing call does not work 2) Calls where occasionally disconnected during testing
Samsung SGH-i550	i550.012	3.0	OK	OK	OK ¹⁾	OK	OK	Not available	1) Sim contacts isn't transferred
Samsung SGH-L170	L1700.05	3.0	OK	OK	OK ¹⁾	OK	OK	Not available	1) Some special characters are not shown correctly
Samsung SGHL700	L700XBIB1	3.0	OK	OK ¹⁾	OK	NOK	OK	Not available	1) Answering using BTP no audio in HFS
Siemens / BenQ									
Siemens C55	V 24	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 054	1) Only cradle, no Bluetooth
Siemens C65	V 25	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 065	1) Only cradle, no Bluetooth
Siemens C75	SW 22 , 19.11.2005	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 381	1) Only cradle, no Bluetooth
Siemens CX65	V 16	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 052	1) Only cradle, no Bluetooth
Siemens CX70	V 34	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 052	1) Only cradle, no Bluetooth
Siemens CX75	SW 13 , 09.01.2006	1.0	NOK ¹⁾	OK	OK	OK	OK	93 199 333	1) Unstable Bluetooth connection with some software versions
Siemens M55	V 91	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 054	1) Only cradle, no Bluetooth
Siemens M65	V 25	1.0	NOK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 052	1) Only cradle, no Bluetooth
Siemens M75	SW 23 , 10.05.2005	1.0	NOK ¹⁾	OK	OK	OK	OK	93 199 334	1) Unstable Bluetooth connection with some software versions
Siemens S55	V 91	1.0	OK ¹⁾	OK	OK	OK	NA ¹⁾	93 199 054	1) Pairing must be done by phone
Siemens S65	V43	1.0	NOK ¹⁾	OK	OK	OK	OK	93 199 055	1) Unstable Bluetooth connection with some software versions
Siemens S75	SW 38 , 29.12.2005	1.0	NOK ¹⁾	OK	OK	OK	OK	93 199 363	1) Unstable Bluetooth connection with some software versions
Siemens SP65	V47	1.0	NOK ¹⁾	OK	OK	OK	OK	93 199 055	1) Unstable Bluetooth connection with some software versions
Sony Ericsson									
Sony Ericsson C702	R3CA037	3.0	OK ^{1,2)}	OK	OK	OK	OK	Not available	1) Does not automatically switch from "Private mode" to Hands free, when getting in range or after ignition on. 2) occasionally you need to restart the phone after disconnecting from HFS to get audio in phone.
Sony Ericsson C902	R3CA038	3.0	OK ^{1,2)}	OK	OK	OK	OK	Not available	1) Does not automatically switch from "Private mode" to Hands free, when getting in range or after ignition on.
Sony Ericsson G502i	R1FA035	3.0	OK ¹⁾	OK	OK	OK ²⁾	OK	Not available	1) Does not automatically switch from "Private mode" to Hands free, when getting in range or after ignition on. 2) No number matching to SIM contacts
Sony Ericsson G700i	1203-5567 R1F02	3.0	OK ¹⁾	OK	OK ²⁾	OK	OK	Not available	1) Does not automatically switch from "Private mode" to Hands free, when getting in range or after ignition on. 2) SIM Contacts isn't transferred
Sony Ericsson G900i	PHONE: 1203-6566 R9L004 BLUETOOTH: 1200-5567 R1D	3.0	OK ¹⁾	OK	OK ²⁾	OK	OK ¹⁾	Not available	1) Does not automatically switch from "Private mode" to Hands free, when getting in range or after ignition on. 2) SIM Contacts isn't transferred
Sony Ericsson G900i	PHONE: 1203-6566 R9L004 BLUETOOTH: 1200-5567 R1D	2.0	OK ¹⁾	OK	OK ²⁾	NOK ³⁾	OK ¹⁾	Not available	1) Does not automatically switch from "Private mode" to Hands free, when getting in range or after ignition on. 2) SIM Contacts isn't transferred 3) Only last dialled number is shown in call list.
Sony Ericsson Hazel	R7BA081	4.0	OK ¹⁾	OK	OK	COK ²⁾	OK	Not available	1) When losing network bluetooth connection is also lost. 2) Number type not displayed in call list.
Sony Ericsson J10i2 ELM	1231-1917	4.0	OK ¹⁾	OK	OK	OK	OK	Not available	1) Have to choose "Source - UHP" in phone meny to direct sound to car.
Sony Ericsson Jalous	R1HA035	4.0	COK ¹⁾	COK ^{1,2,3)}	OK	OK	OK	Not available	1) Intermittent connection issues noticed. 2) Call made by phone with Hands free off will be "Private" when
Sony Ericsson K510i	R4EA031	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from "Private mode" to Hands free, when getting in range or after ignition on.
Sony Ericsson K530	R6BC002	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from "Private mode" to Hands free, when getting in range or after ignition on.
Sony Ericsson K530	R8BE001	3.0	OK	OK	OK ¹⁾	OK	OK ²⁾	Not available	1) SIM Contacts not transferred 2) Does not automatically switch from "Private mode" to Hands free, when getting in range or after ignition on.

Supported phones	Phone software The software version in your phone (refer to manual or manufacturer on how to check it)	Saab Bluetooth Handsfree system S/W version. See production interval table for detailed information	Bluetooth Connection Stability of the connection between phone and vehicle system	Hands Free Dialling ability to dial from vehicle HMI	Phone book Access in vehicle HMI	Call list Access in vehicle HMI	Private mode Switch audio between vehicle and phone	Cradle part number	Comments / Deviations
Sony Ericsson K610i	R1ED001	3.0	OK ¹⁾	OK	OK ²⁾	OK	OK	Not available	1) Sometimes not auto connected when coming into range 2) SIM Contacts not transferred
Sony Ericsson K610i	R1ED001	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson K630	R1CA029	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson K630	R1EA030	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson K630	R1EA030	3.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson K660i	R1EA030	3.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson K660i	R1EA030	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson K700i	R2AE033	1.0	OK	OK	NOK ¹⁾	OK	OK	93 199 056	1) Partly no or incomplete transmission of phone book entries both in cradle mode as well as in Bluetooth mode.
Sony Ericsson K750i	Unknown	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson K750i	R1N035	1.0	OK	OK	NOK ¹⁾	OK	OK	93 199 543	1) Partly missing contacts
Sony Ericsson K770i	R8AA018	3.0	OK	OK	OK ²⁾	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on. 2) SIM-contacts not transferred
Sony Ericsson K770i	R8AA018	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson K800i	R1GB001	3.0	OK	OK	OK ¹⁾	OK	OK	Not available	1) SIM-contacts not transferred
Sony Ericsson K800i	R1G001	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson K810i	R6BC002	3.0	OK	OK	OK ²⁾	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on. 2) SIM-contacts not transferred
Sony Ericsson K810i	R6BC002	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson K850i	R1CA029	3.0	OK	OK	NT	NT	NT	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson K850i	R1CA029	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson K850i	R1FA035	3.0	OK ¹⁾	OK	OK	OK	OK	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson M600i	R9A002, R9EA002	1.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson P1i	Phone: CXC162037 R9H004 Bluetooth: CXC162143 R1D Organizer: CXC162108 R6E30	2.0	OK ¹⁾	OK	OK ²⁾³⁾	OK	OK	Not available	1) Some BT instability problem has been seen 2) vCard information displayed as e.g. /1 and /2 etc instead of /W and /H for Work and Home phone number. 3) Long time for phone book to download
Sony Ericsson P1i	CXC 162037 R9K009	3.0	OK ¹⁾	OK	OK ²⁾	OK	OK	Not available	1) Some BT instability problem has been seen. 2) SIM Contacts isn't transferred
Sony Ericsson Satio	R2AK006 (ver) 1218-9500 (id)	4.0	OK ¹⁾	COK ²⁾	OK	OK	OK	Not available	1) When connecting to Hands free while getting an incoming call the corresponding symbol will be shown but no ringtone will be heard and the call cannot always be accepted by pressing Hands free phone button. 2) Incoming calls can at times not be accepted / declined from Hands free. Phone is not recommended.
Sony Ericsson Satio	R1BB041	3.0	OK	OK ¹⁾	OK	OK	OK	Not available	1) No ring tone from HFS system
Sony Ericsson T610	V R6C005	1.0	OK	OK	NOK ¹⁾	OK	OK	93 199 057	1) Long transmission time for phone book entries
Sony Ericsson T630	V R7A011	1.0	OK	OK	NOK ¹⁾	OK	OK	93 199 057	1) Long transmission time for phone book entries
Sony Ericsson T630	V R7A011	3.0	OK ¹⁾	OK	OK	OK	OK	93 199 057	1) some Bluetooth stability issues seen.
Sony Ericsson T700	R3DA024	3.0	OK	OK	OK	OK	OK	Not available	
Sony Ericsson W302	R1AA030	3.0	OK	OK ¹⁾	OK ²⁾	NOK	NOK ³⁾	Not available	1) Bluetooth connection dropped if incoming call is answered by phone HMI 2) SIM contacts isn't transferred 3) Bluetooth connection lost if call is transferred from Hands free system to the phone
Sony Ericsson W350i	R10AB002	3.0	OK	OK	OK ¹⁾	OK	OK	Not available	1) SIM Contacts isn't transferred
Sony Ericsson W380i	R9BB001	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson W380i	1201-4421 R9BB001 080212	3.0	OK	OK	OK ¹⁾	OK	OK	Not available	1) SIM Contacts isn't transferred
Sony Ericsson W580i	R6BC002	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson W580i	R8BE001	3.0	OK	OK	OK ¹⁾	OK	OK	Not available	1) SIM-contacts not transferred
Sony Ericsson W595	R3DA024	3.0	OK	OK	OK	OK	OK	Not available	
Sony Ericsson V640	R1CA029	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson V640	R1EA030	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.

Supported phones	Phone software The software version in your phone (refer to manual or manufacturer on how to check it)	Saab Bluetooth Handsfree system S/W version. See production interval table for detailed information	Bluetooth Connection Stability of the connection between phone and vehicle system	Hands Free Dialling ability to dial from vehicle HMI	Phone book Access in vehicle HMI	Call list Access in vehicle HMI	Private mode Switch audio between vehicle and phone	Cradle part number	Comments / Deviations
Sony Ericsson V640	R1EA030	3.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson W660i	R8BB001	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson W660i	R8BB001	3.0	OK	OK	OK ¹⁾	OK	OK	Not available	1) SIM-contacts not transferred
Sony Ericsson W700i	-	1.0	OK	OK	NOK ¹⁾	OK	OK	93 199 543	1) Partly missing contacts
Sony Ericsson W710i	R1JC002	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson W710i	R1JC002	3.0	OK	OK	OK ¹⁾	OK	OK	Not available	1) SIM-contacts not transferred
Sony Ericsson W760i	R3BA035	3.0	OK	OK	OK ¹⁾	OK	OK	Not available	1) Occasionally phone book not downloaded. Ok after ignition cycle
Sony Ericsson W800i	R1BC002	1.0	OK	OK	NOK ¹⁾	OK	OK	93 199 543	1) Partly missing contacts
Sony Ericsson W880i	R8BA024	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson W880i	R8BE001	3.0	OK	OK	OK ¹⁾	OK	OK	Not available	1) SIM-contacts not transferred
Sony Ericsson W890	R1EA030	3.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson W890i	R1FA035	3.0	OK ¹⁾	OK	OK	OK	OK	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson W890i	R1EA030	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson W902	R3DA026	3.0	OK	OK	OK	OK	OK	Not available	
Sony Ericsson W910	R1EA030	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson W910i	R1CA029	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson W910i	R1FA035	3.0	OK ¹⁾	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson W960i	Phone: R9J005 Bluetooth: CXC162143 R1D Organizer: CXC162146 R6F41 CDA: CDA162032/1 R6F40	2.0	OK ¹⁾	OK	OK ^{2) & 3)}	OK	OK	Not available	1) Some instability. 2) vCard information displayed as e.g. /1 and /2 etc instead of /W and /H for Work and Home phone number. 3) Long time for phone book to download, approx. 3 minutes
Sony Ericsson W960i	Phone: CXC 162037 R9K009	3.0	OK ¹⁾	OK	OK ²⁾	OK	OK	Not available	1) occasionally phone doesn't auto connect at start up during ongoing call. 2) SIM Contacts isn't transferred
Sony Ericsson W980	R3CA033	3.0	OK	OK ¹⁾	OK	OK	OK	Not available	1) Low volume on land side
Sony Ericsson W995	R1HA035	4.0	OK	OK	OK	OK	OK	Not available	
Sony Ericsson Vivaz	1224-4699-R2AA029	4.0	OK	OK	OK	NOK ¹⁾	OK	Not available	1) Call lists only shows phone numbers, not contact names.
Sony Ericsson X1	R1AA017	3.0	OK	OK	NOK ¹⁾	NOK ¹⁾	OK	Not available	1) Not all contacts are transferred
Sony Ericsson XPERIA X2	R1AA097 (ver) 1230-2397 (id)	4.0	NOK ^{1, 2)}	NOK ²⁾	OK	OK	OK	Not available	1) Hands free shows bluetooth connection to Phone but no symbol in display and no ringtone during incoming call. 2) Cannot answer or decline an incoming call with Hands free buttons, only by using Phone buttons. No ringtone for incoming calls, only the symbol is displayed. Phone is not recommended .
Sony Ericsson XPERIA X10	SW: 1.6 Kernel: 2.6.29	4.0	OK	OK	COK ^{1, 2)}	OK	OK	Not available	1) Does not support all special characters. 2) Does not support vCard.
Sony Ericsson XPERIA X10i	SW: 2.1 (update) Rev. 2.0.A.0.504	4.0	OK	COK ¹⁾	NOK ²⁾	NOK ³⁾	OK	Not available	1) Bluetooth connection lost when call is ended due to lost network. 2) Phonebook is not correctly updated. Numbers will include separators in numbers not containing a land code (like +46) before number. I.e. 111222333 will be shown as 111-222-333. Many contacts are not transferred and names with special characters will present issues. 3) When using voice command, the name from phone book does not appear in call list - just the phone number.
Sony Ericsson XPERIA X10 Mini	SW: 1.6 Kernel: 2.6.29	4.0	OK	OK	COK ^{1, 2)}	OK	OK	Not available	1) Does not support all special characters. 2) Does not support vCard.
Sony Ericsson Yari	R1BA044	3.0	OK	OK ¹⁾	OK ²⁾	OK	OK	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on. 2) Some special characters missing
Sony Ericsson Yari U100i	R1BA044	4.0	OK	OK	OK	OK	OK	Not available	
Sony Ericsson Z555i	1202-6764 R9BB001 080212	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson Z555i	R10CA001	3.0	OK	OK ¹⁾	OK ²⁾	OK	OK ³⁾	Not available	1) occasionally ring tone disappear. 2) SIM Contacts isn't transferred 3) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson Z750	R1CA029	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson Z750	R1EA030	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson Z750	R1EA030	3.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.

Supported phones	Phone software The software version in your phone (refer to manual or manufacturer on how to check it)	Saab Bluetooth Handsfree system S/W version. See production interval table for detailed information	Bluetooth Connection Stability of the connection between phone and vehicle system	Hands Free Dialling ability to dial from vehicle HMI	Phone book Access in vehicle HMI	Call list Access in vehicle HMI	Private mode Switch audio between vehicle and phone	Cradle part number	Comments / Deviations
Sony Ericsson Z770	R1EA030	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson Z770	R1EA030	3.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson Z770i	R1EA022	2.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.
Sony Ericsson Z770i	R1EA022	3.0	OK	OK	OK	OK	OK ¹⁾	Not available	1) Does not automatically switch from 'Private mode' to Hands free, when getting in range or after ignition on.